

HCC TRACKS DATA

Hikoikoi	Harbour Ward
Time	40 min
Length	1484m
Likely predominant users	Urban Resident
Track classification	Path
Track type	Short coastal walk, well defined trails, pushchair, wheel chair and cycle friendly
Track width	1000 to 1300mm, but 800mm on boardwalk section
Gradient	almost flat, but section by St James Sea Scouts too steep for wheelchair
Track surface	lime stabilised top course and asphalt
Track surface condition	fair
Drainage	crowned
Drainage condition	all weather, no noticeable problems
Steps	timber, associated with 3 viewing platforms
Step condition	fair
Structures	4 timber platforms, boardwalk with non-skid product
Structure condition	good
Barriers	timber handrails
Barrier condition	good
Signage	customised Hikoikoi Reserve signage, interpretative panel at Hikoikoi car park
Signage condition	fair
Features	Attractive easy trail with river and estuary views, beach, hard court and sports grounds, harbour views, lookouts, toilets, kiosk
Best eventual fit within NZS	Path
Considerations	

Petone Foreshore East	Harbour Ward
Time	
Length	550m
Likely predominant users	Urban Resident
Track classification	Path
Track type	Short coastal walk, well defined trail, pushchair, wheel chair and cycle friendly
Track width	greater than 1200
Gradient	almost flat
Track surface	asphalt, aggregate concrete
Track surface condition	fair
Drainage	promenade drains through seawall
Drainage condition	all weather, although sand build up can be problematic behind buildings
Steps	connecting beach to promenade
Step condition	excellent although sand accumulation can be problematic
Structures	3 decks, 1 boardwalk
Structure condition	excellent
Barriers	bollards separate vehicles from promenade in some stretches
Barrier condition	excellent
Signage	no track signs present, probably none required
Signage condition	mixed condition, rationalisation required
Features	Beaches, Harbour views, Art works, National memorial, Settlers Museum, Lookout platforms, Yacht and Rowing clubs, Picnic areas, BBQs, Changing rooms, Toilets, Cafe, Gardens featuring native coastal and threatened species
Best eventual fit within NZS	Path
Considerations	Providing greater separation of pedestrians and vehicles. Extending exposed aggregate paving. Installing night lighting

Petone Foreshore West	Harbour			
Time	10 min.			
Length	14-Jan-01			
Likely predominant users	Urban Resident			
Track classification	Path			
Track type	Short coastal walk, well defined trail, pushchair, wheelchair and cycle friendly			
Track width	1.2m			
Gradient	almost flat			
Track surface	lime stabilised top course			
Track surface condition	good although recent maintenance has resulted in substandard, obvious patches			
Drainage	crowned	max riser	min riser	av. riser
Drainage condition	all weather, no problems noted	min tread	max tread	av. tread
Steps	connecting trail to beach	min width	max width	av. width
Step condition	fair			
Structures	2 small decks, connected to beach with steps and ramp			
Structure condition	excellent			
Barriers				
Barrier condition				
Signage	Compacted base course. Generally in good condition.			
Signage condition				
Features	Wharf, Beach, Harbour views, seats, Lookout platforms, car parking, Toilets, cafes and car parking very nearby			
Best eventual fit within NZS	Path			
Considerations	area seaward of trail warrants upgrade in keeping with slightly "wild" character			

Te Mome Stream	Harbour
Time	
Length	
Likely predominant users	Short Stop Traveller
Track classification	Tramping Track
Track type	sections of gravel and grass well used by local walkers and cyclists
Track width	200mm to 400mm
Gradient	easy
Track surface	gravel and grass
Track surface condition	poor
Drainage	poor
Drainage condition	compressed trail surface impedes year round use
Steps	
Step condition	
Structures	
Structure condition	
Barriers	
Barrier condition	
Signage	timber at Bracken Street
Signage condition	poor
Features	runs alongside Te Mome Stream, Bracken Street to eastern end Jackson Street
Best eventual fit within NZS	Short Walk
Considerations	Simple task to upgrade this to all weather Short Walk or even Path for wheelchairs, buggies and bicycles

Korokoro Gateway Swale	Harbour
Time	7min
Length	228m
Likely predominant users	Urban Residents
Track classification	Path
Track type	Short coastal walk elevated well above water, well defined trail, pushchair, wheelchair and cycle friendly
Track width	1200 to 2600mm
Gradient	almost flat
Track surface	asphalt and compacted top course
Track surface condition	good
Drainage	
Drainage condition	no problems
Steps	
Step condition	
Structures	timber boardwalk at western end
Structure condition	good
Barriers	
Barrier condition	
Signage	
Signage condition	
Features	contemporary landscaping, extensive car parking, toilet
Best eventual fit within NZS	Path
Considerations	rock work next to asphalt path is unsightly, timber edge of path requires frequent repairs, adjacent turf is failing

Centenary Lookout	Harbour
Time	3min return
Length	184m
Likely predominant users	Urban Residents (local to suburb)
Track classification	Short walk questionable
Track type	Short uphill climb on benched track
Track width	900mm
Gradient	moderately steep slope to flat top area.
Track surface	compacted top course
Track surface condition	fair, rutting occurring down centre of track
Drainage	fair
Drainage condition	water directed down track is causing deterioration
Steps	yes
Step condition	good
Structures	
Structure condition	
Barriers	24m timber handrails
Barrier condition	fair
Signage	standard HCC on-street and on-track signage provided
Signage condition	good
Features	harbour view with seat and picnic table near summit
Best eventual fit with NZS	Short Walk width and gradient limit upgrade to path
Considerations	constructed by local volunteers in late 1990s, interpretive sign at top??

Zig Zag	Harbour
Time	10 min
Length	184m
Likely predominant users	
Track classification	Easy Tramping Track
Track type	short walk with long, steep sections, through bush along residential fringe, linking roads.
Track width	300 to 1000mm
Gradient	steep
Track surface	earth some benched sections
Track surface condition	poor Slippery in parts. Steep sections with loose gravel.
Drainage	
Drainage condition	steep cross fall in places,
Steps	additional required plus landings
Step condition	good
Structures	Bridge at stream junction may improve winter use
Structure condition	good needs to be checked
Barriers	
Barrier condition	
Signage	standard HCC on-street and on-track signage, additional on-track signage required for clarity at stream junction
Signage condition	good
Features	Stream, Coastal forest.
Best eventual fit within NZS	Short Walk Steepness of track, width of track, slippery due to loose surface material on very steep sections, earth steps.
Considerations	Older section of track in poor condition. Improve track definition. Re-routing sections warranted.

Wet Foot Track	Harbour
Length	Note around 12 min from Akatea Rd play area lawn to Singers Rd Playcentre lawn. 775m
Likely predominant users	Day Visitor
Track classification	Tramping Track
Track type	Steep, narrow short trail along stream bed through bush along residential fringe, linking roads.
Track width	300 to 750mm
Gradient	
Track surface	earth, rock, roots, stream bed
Track surface condition	poor, loose surface material on steeper sections is slippery
Drainage	
Drainage condition	
Steps	11 in various styles and dimensions of inground steps
Step condition	poor
Structures	
Structure condition	
Barriers	
Barrier condition	
Signage	standard HCC signage on-street and on-track
Signage condition	
Features	Stream, Coastal forest.
Best eventual fit within NZS	Walking Track Location right in gully/stream is problematic
Considerations	Benching, steps, and trail definition required. Multiple stream crossings in Gully, rocky stream bed. Narrow, steep sections

Dry Foot Track	Harbour
Time	20 min.
Length	349m
Likely predominant users	Day Visitor
Track classification	Tramping Track
Track type	Steep, narrow short trail along stream bed through bush along residential fringe, linking roads.
Track width	300 to 750mm
Gradient	
Track surface	earth, rock, roots, stream bed
Track surface condition	poor, loose surface material on steeper sections is slippery
Drainage	
Drainage condition	
Steps	11 in various styles and dimensions of inground steps
Step condition	poor
Structures	A lookout platform/deck could be added if trail were upgraded.
Structure condition	
Barriers	
Barrier condition	
Signage	standard HCC signage on-street and on-track
Signage condition	
Features	Stream, Coastal forest, which exits to lower Korokoro Road
Best eventual fit within NZS	Walking Track
Considerations	Benching, steps, handrail, trail definition required, very steep scramble up ridge to site of ex-pine plantation. Is track is justified?

O'Donohoos Track	Harbour
Time	15 min
Length	889m
Likely predominant users	Short Stop Traveller at least to Sugarloaf intersection
Track classification	Tramping Track
Track type	Short trail through regenerating scrub/bush, linking Akatea Road and Maungaraki Road, connect to Sugarloaf
Track width	300mm to 1000mm
Gradient	medium
Track surface	earth, rock, roots
Track surface condition	fair, would benefit from professional work
Drainage	fair, would benefit from professional work
Drainage condition	will rut in medium term
Steps	timber
Step condition	more required
Structures	
Structure condition	
Barriers	
Barrier condition	
Signage	Standard HCC signage on-street and on-track. Directional map panel at Maungaraki Road.
Signage condition	Good. Add more at sugarloaf intersection.
Features	Regenerating scrub/bush, links to other tracks and creates loop opportunities.
Best eventual fit within NZS	Short Walk between Maungaraki Road and Sugarloaf intersection. Remainder possibly Walking Track
Considerations	Built by volunteers in early 2000s
Sugarloaf	Harbour
Time	10min
Length	221m
Likely predominant users	Short Stop Traveller
Track classification	Tramping Track
Track type	Short walk track through regenerating and mature bush along residential fringe, linking roads.
Track width	300 to 1000mm, could easily meet 750mm standard
Gradient	Generally comfortable east of sugarloaf. Precarious, rocky section between Sugar Loaf and O'Donohoos.
Track surface	earth, rock, roots
Track surface condition	Slippery in parts. Steep sections with loose gravel. Some stumps on or at edge of track.
Drainage	
Drainage condition	steep cross fall
Steps	many, various styles of construction and dimensions
Step condition	
Structures	
Structure condition	
Barriers	
Barrier condition	
Signage	
Signage condition	
Features	Harbour/city Lookout, direct links to other tracks.
Best eventual fit within NZS	Short Walk
Considerations	steep, natural slopes require steps to reduce difficulty and risk of slipping over
Bulldozer Track	Harbour
Time	35min
Length	690m
Likely predominant users	Day Visitor
Track classification	Tramping Track
Track type	Short walk track through bush along residential fringe, linking roads.
Track width	300 to 750mm
Gradient	steep
Track surface	earth, many tree roots and some areas of rock
Track surface condition	
Drainage	
Drainage condition	
Steps	
Step condition	
Structures	
Structure condition	
Barriers	
Barrier condition	
Signage	Standard HCC signage on-street and on-track, simple map panel at Maungaraki Road entrance
Signage condition	additional route markers required to clarify direction, map panel required at George Gee Drive entry
Features	Attractive vegetation. Links to Sugarloaf and Kohekohe climb and contributes to circuit opportunities.
Best eventual fit within NZS	Walking track Width in parts. Steepness of track in parts. Uneven treads and risers on steps.
Considerations	This track requires professional design if upgrading is to be considered. Korokoro Side of the Sugarloaf track is sub-standard

Jaggers Track

Time	15m
Length	271m
Likely predominant users	Day Visitor
Track classification	Tramping Track
Track type	marked trail, some roughly benched sections with steep, rocky climb
Track width	200 to 600mm
Gradient	steep
Track surface	earth, rocks and many tree roots
Track surface condition	poor
Drainage	
Drainage condition	some ruts forming on benched sections
Steps	
Step condition	fair, ruts beginning to form as a result of surface deterioration
Structures	
Structure condition	
Barriers	ought to be considered on climb from Kohekohe Climb to Bulldozer Track
Barrier condition	
Signage	required
Signage condition	
Features	Narrow, steep, uneven track surface
Best eventual fit with NZS	Walking Track requires significant remedial work to achieve NZS
Considerations	This track requires professional design and construction to contribute properly to Kohekohe Climb/Bulldozer/Sugarloaf circuit

Kohekohe Climb

Time	
Length	780m
Likely predominant users	Day Visitors
Track classification	Tramping Track
Track type	earth track
Track width	
Gradient	medium
Track surface	earth, with rock and tree roots
Track surface condition	poor, slippery even in dry weather
Drainage	
Drainage condition	track needs to be diverted from low points and benched
Steps	many more steps required
Step condition	
Structures	timber staircase at Acacia Ave
Structure condition	good
Barriers	
Barrier condition	
Signage	Standard HCC signage on-track
Signage condition	good
Features	
Best eventual fit with NZS	Walking Track some upgrading, route definition and steps required to achieve NZS
Considerations	This is a key track, which could link to a new, easy grade track into middle Maungaraki

Dowse Track

Harbour

Time	3min
Length	
Likely predominant users	Short Stop Traveller
Track classification	Walking Track
Track type	Short walkthrough bush into Percy Scenic Reserve Aviary Lawn
Track width	1000mm
Gradient	steep
Track surface	loose gravel
Track surface condition	replace with lime stabilised top course or compacted top course
Drainage	no problems reported
Drainage condition	
Steps	inbuilt timber steps with timber handrail
Step condition	excellent
Structures	one seat
Structure condition	
Barriers	timber
Barrier condition	excellent
Signage	customised HCC signage
Signage condition	good
Features	Amenity gardens.
Best eventual fit within NZS	Short Walk
Considerations	Not cycle or baby buggy friendly. Too many steps and too steep, given the users and popularity of destination

Jasmine Track	Harbour
Time	10min
Length	
Likely predominant users	Short Stop Traveller
Track classification	Tramping Track
Track type	narrow track through bush that connects pond to Stanhope Grove car park
Track width	700 to 1200mm
Gradient	medium
Track surface	earth, roots, rutted, well defined trail
Track surface condition	poor, requires maintenance and timber edge on parts of track to retain
Drainage	rebenching required
Drainage condition	
Steps	timber, most with timber stringers
Step condition	fair
Structures	
Structure condition	
Barriers	
Barrier condition	
Signage	present
Signage condition	
Features	Amenity gardens. Nice native bush.
Considerations	requires upgrading to meet needs of anticipated users

Ratanui Circuit

Time	10min
Length	
Likely predominant users	Short Stop Travellers but possibly Day Visitors
Track classification	Tramping Track
Track type	loop track linking pond area to Stanhope Grove and Beech Track
Track width	
Gradient	
Track surface	
Track surface condition	
Drainage	
Drainage condition	
Steps	
Step condition	
Structures	
Structure condition	
Barriers	
Barrier condition	
Signage	
Signage condition	
Features	Remnant residential garden mixed with native bush, has historical interest
Best eventual fit within NZS	Short Walk
Considerations	

Beech Track

Time	
Length	
Likely predominant users	Short Stop Traveller
Track classification	Tramping Track
Track type	newly installed one way access to large beech tree
Track width	
Gradient	medium
Track surface	earth
Track surface condition	good
Drainage	
Drainage condition	
Steps	
Step condition	
Structures	
Structure condition	
Barriers	
Barrier condition	
Signage	
Signage condition	
Features	set amongst remnant garden of Hector estate
Best eventual fit within NZS	Short Walk
Considerations	inadequately constructed, given potential users

Access Track	Western
Time	5 min
Length	
Likely predominant users	Day Visitor
Track classification	Walking Track
Track type	Short walking track through bush to lookout, can cope with bicycles and baby buggies
Track width	2500mm plus
Gradient	medium
Track surface	gravel
Track surface condition	good, but really too loose for easy downhill walking
Drainage	side drains
Drainage condition	good
Steps	
Step condition	
Structures	
Structure condition	
Barriers	
Barrier condition	
Signage	customised HCC signage, more required for clarification, especially at street end
Signage condition	
Features	Amongst amenity gardens and bush
Best eventual fit within NZS	Walking track
Considerations	Provides contractors with vehicle access into site from Stanhope Grove
<hr/>	
Frank Cameron Track	Harbour
Time	5min
Length	
Length - Pedometer Steps	200 A further 200 to Frank Cameron London road entrance.
Likely predominant users	Day Visitor
Track classification	Walking Track
Track type	short walking track through bush with large section of steps and staircase
Track width	300 to 1200mm
Gradient	very steep, but overcome with steps
Track surface	lime stabilised top course
Track surface condition	good
Drainage	crowned track, side drains, culvert and novaflow cross drains
Drainage condition	good - ruts develop around 15m uphill of top of staircase
Steps	timber
Step condition	excellent
Structures	2 open side shelters, timber staircase and landings, complying with NZS
Structure condition	excellent
Barriers	timber handrails, complying with NZS
Barrier condition	excellent
Signage	standard HCC signage on-track and on-street, interpretive panel at Frank Cameron
Signage condition	good
Features	Pleasant access between Percy Scenic Reserve and Frank Cameron Park
Best eventual fit within NZS	Walking Track
Considerations	Designed professionally and built by contractor in 2007
<hr/>	
Waterfall Track	Harbour
Time	15min
Length	
Likely predominant users	Short Stop Traveller
Track classification	Tramping Track
Track type	Short well defined, partially benched trail through bush and stream to bottom of water fall
Track width	500 to 1500mm
Gradient	medium
Track surface	earth, rock, roots and stream bed
Track surface condition	poor, uneven, too narrow in appropriate given likely users
Drainage	poor
Drainage condition	track is rutted and boggy in places
Steps	timber
Step condition	poorly maintained, non-complying
Structures	inappropriate, given likely users
Structure condition	steps of immediate concern
Barriers	inappropriate, given likely users
Barrier condition	poor
Signage	no indication of difficulty of track and structures
Signage condition	
Features	Regenerating native bush, access to stream edge but obscured view of Waterfall from track end
Best eventual fit within NZS	Short Walk
Considerations	Massive potential to be first bush experience for families and school parties. Track requires URGENT professional attention

Waterfall Route

Time	
Length	
Likely predominant users	Day Visitor
Track classification	Route
Track type	interesting route between waterfall and Barberry Grove
Track width	200 to 400mm
Gradient	steep
Track surface	earth, roots and rock
Track surface condition	fair
Drainage	
Drainage condition	
Steps	timber risers, uneven, steep
Step condition	fair
Structures	
Structure condition	
Barriers	
Barrier condition	
Signage	
Signage condition	no warning of condition/difficulty of route from either end
Features	passes alongside waterfall
Best eventual fit within NZS	Walking Track
Considerations	This is very poor, given the connection to Percy Scenic Reserve and Maungaraki

Rata Track

Time	
Length	
Likely predominant users	Short Stop Traveller
Track classification	Tramping Track
Track type	newly opened track
Track width	
Gradient	easy
Track surface	
Track surface condition	
Drainage	
Drainage condition	
Steps	
Step condition	
Structures	
Structure condition	
Barriers	
Barrier condition	
Signage	
Signage condition	
Features	Passes through/near remnant plantings of old Hector estate
Best eventual fit within NZS	Short Walk
Considerations	Much of site owned by Transit

Pond Circuit

Time	
Length	
Likely predominant users	Urban Resident
Track classification	Path
Track type	asphalt paths that surround lawns and pond in figure 8 shape
Track width	
Gradient	easy
Track surface	asphalt paths
Track surface condition	good
Drainage	
Drainage condition	no issues
Steps	none
Step condition	
Structures	
Structure condition	
Barriers	
Barrier condition	
Signage	
Signage condition	
Features	
Best eventual fit within NZS	Path
Considerations	

Collections Drive

Time	
Length	
Likely predominant users	Urban Resident
Track classification	Path
Track type	link between pond and lawn, plantings on both sides of path
Track width	asphalt
Gradient	easy
Track surface	
Track surface condition	
Drainage	no issues
Drainage condition	
Steps	none
Step condition	
Structures	
Structure condition	
Barriers	
Barrier condition	
Signage	
Signage condition	
Features	passes near water wheel
Best eventual fit within NZS	Path
Considerations	

Southern Link

Time	
Length	
Likely predominant users	Short Stop Traveller
Track classification	Easy Tramping Track
Track type	links lawn near waterfall with Jasmine Track and Ratanui Tracks
Track width	
Gradient	medium
Track surface	
Track surface condition	
Drainage	
Drainage condition	
Steps	
Step condition	
Structures	
Structure condition	
Barriers	
Barrier condition	
Signage	
Signage condition	
Features	
Best eventual fit within NZS	Short Walk
Considerations	

Mulberry Track

Time	15min
Length	861m
Likely predominant users	Urban Resident
Track classification	Easy Tramping Track
Track type	Short track through bush gully along residential fringe, linking roads
Track width	300 to 2000mm
Gradient	medium, with small steep sections
Track surface	earth, gravel, roots
Track surface condition	poor, loose gravel
Drainage	good
Drainage condition	
Steps	variety of timber construction
Step condition	fair but inconsistent and more required
Structures	
Structure condition	
Barriers	timber rail
Barrier condition	fair
Signage	Track closed while D2P construction underway
Signage condition	
Features	Flood Retention Dam. Links to Hibiscus Grove
Best eventual fit within NZS	Short Walk
Considerations	This track could provide residents with an active transport option

Camel's Hump	Western
Time	4 min each way
Length	181m
Likely predominant users	Short Stop Traveller
Track classification	Walking Track
Track type	short, pleasant trail to simple lookout
Track width	600mm
Gradient	Gentle
Track surface	compacted top course
Track surface condition	fair, top course loose in places. Additional steps and lime dressing would assist.
Drainage	cross drains
Drainage condition	poor cross drains need maintenance
Steps	timber
Step condition	good
Structures	
Structure condition	
Barriers	
Barrier condition	
Signage	Standard HCC signage on-street
Signage condition	good
Features	Panoramic views. Rock outcrop.
Best eventual fit within NZS	Short Walk
Considerations	Walking Track

Minoh House to lower car park	Western
Time	2 min
Length	82m
Likely predominant users	Short Stop Traveller
Track classification	Walking Track
Track type	short, narrow, stepped trail linking house and driveway to lower car park
Track width	600 to 1300mm
Gradient	medium
Track surface	asphalt and concrete
Track surface condition	poor
Drainage	
Drainage condition	
Steps	many
Step condition	poor
Structures	
Structure condition	
Barriers	timber handrail
Barrier condition	excellent
Signage	customised HCC signage on track (red tones)
Signage condition	good
Features	rock retaining wall, attractive woodland planting at upper section
Best eventual fit within NZS	Short Walk
Considerations	felling large, mature pines around track may open opportunities to reroute and reduce gradient

Pond to lower car park	Western
Time	3 min
Length	204m
Likely predominant users	Short Stop Traveller
Track classification	Walking Track
Track type	short, easy gravel access road to pond and fernery
Track width	201 to 3000mm
Gradient	easy
Track surface	base course
Track surface condition	needs regarding and resupply of compacted top course
Drainage	uneven, water ponds
Drainage condition	poor
Steps	
Step condition	
Structures	
Structure condition	
Barriers	fence separates access road from SH2
Barrier condition	fair
Signage	customised HCC signage, red tones
Signage condition	good
Features	
Best eventual fit within NZS	Short Walk
Considerations	planting and regrading would improve presentation

Fernery Trail	Western
Time	1min
Length.	60m
Likely predominant users	Short Stop Traveller
Track classification	Short Walk
Track type	Short easy walk track along access road to old fern house pond area.
Track width	
Gradient	easy
Track surface	
Track surface condition	poor, was formed to 1200mm in 2004
Drainage	
Drainage condition	
Steps	one
Step condition	good
Structures	one
Structure condition	good
Barriers	
Barrier condition	
Signage	customised HCC signage on track (red tones)
Signage condition	good
Features	Historic fern house remains.
Best eventual fit with NZS	Short Walk
Considerations	poor maintenance (track and vegetation) has resulted in degradation of 2005 renovation
Best eventual fit within NZS	Short Walk
Chimney loop	Western
Time	2 min
Length.	
Likely predominant users	Short Stop Traveller
Track classification	Walking Track
Track type	Short easy loop track in bush.
Track width	1200mm
Gradient	easy
Track surface	earth and gravel
Track surface condition	fair
Drainage	fair, cross fall needs attention
Drainage condition	needs attention to become all weather
Steps	
Step condition	
Structures	bridge
Structure condition	good
Barriers	at front edge of pond
Barrier condition	fair
Signage	not specifically for this track
Signage condition	
Best eventual fit within NZS	Short Walk
Features	Stream with small waterfall/pond.
Considerations	Add signs. pond is really a storm water intake and is no beauty
Pond to Minoh House	Western
Time	4 min
Length.	57m
Likely predominant users	Short Stop Traveller
Track classification	Walking Track
Track type	linking track in bush / gardens.
Track width	500 to 800mm
Gradient	medium
Track surface	earth, rock
Track surface condition	fair, benched width is shrinking as a result of vegetation maintenance
Drainage	small cross drain required
Drainage condition	
Steps	various timber steps
Step condition	fair
Structures	
Structure condition	
Barriers	
Barrier condition	
Signage	customised HCC signage on track (red tones)
Signage condition	good
Features	top exits to timber deck with views of Hutt Valley and Minoh House (front entrance)
Best eventual fit with NZS	Short Walk
Considerations	Improvement would open opportunities to Minoh House visitors

Skate Ramp Link	Western
Time	5 min
Length	
Likely predominant users	Day Visitor
Track classification	Easy Tramping Track
Track type	Short track linking to main walking loops in Jubilee Park
Track width	600 to 800mm
Gradient	medium
Track surface	gravel, earth, roots, rock
Track surface condition	uneven, narrow, requires base and top course
Drainage	may be able to deal with small boggy patches more effectively with surfacing
Drainage condition	fair, a few small boggy patches
Steps	various timber styles
Step condition	fair, many need maintenance/replacing
Structures	
Structure condition	
Barriers	
Barrier condition	
Signage	customised HCC signage on track (red tones)
Signage condition	good. Map board would be useful to illustrate track network layout for site
Features	Waterfall
Best Eventual fit with NZS	Walking Track
Considerations	prioritise attention on set of 26 in ground steps, consider staircase or adding landings

Big Loop	Western
Time	15 min
Length	532m
Likely predominant user	Day Visitor
Track classification	Easy Tramping Track
Track type	Short bush walk track in bush remnant gardens.
Track width	400 to 1200mm
Gradient	medium generally but steeper in places
Track surface	earth, gravel, rocks, tree roots
Track surface condition	uneven, difficult to maintain
Drainage	one cross drain but some boggy patches
Drainage condition	requires professional attention from contractor
Steps	variety of timber and earth steps
Step condition	generally poor, replacement steps and additional steps required
Structures	
Structure condition	
Barriers	
Barrier condition	
Signage	customised HCC signage on track (red tones)
Signage condition	good. Map board would be beneficial to illustrate layout of network
Features	pleasant bush walk close to City
Best eventual fit within NZS	Walking Track
Considerations	

Big Loop Extension	Western
Time	4 min
Length	158m
Likely predominant users	Day Visitor
Track classification	Tramping Track
Track type	Short walk track in bush / gardens.
Track width	700mm
Gradient	medium
Track surface	clay, rock, gravel, roots
Track surface condition	fair
Drainage	needs attention
Drainage condition	slippery when wet
Steps	earth
Step condition	poor, many are eroded
Structures	
Structure condition	
Barriers	
Barrier condition	
Signage	customised HCC signage on track (red tones)
Signage condition	good, but information does not explain loop layout. Map board would be beneficial
Features	Historic ornamental gardens
Best eventual fit within NZS	Walking Track
Considerations	Address track width and upgrade old earth steps.

Rock Wall Track	Western
Time	4 min
Length	138m
Likely predominant users	Day Visitor
Track classification	Tramping Track
Track type	Short walk track in bush / gardens.
Track width	800mm
Gradient	medium
Track surface	clay, rock, gravel, roots
Track surface condition	poor, slippery when wet, professionally surface
Drainage	
Drainage condition	provide some under track to reduce slipperiness
Steps	concrete steps are really too steep but probably best to retain for historic/character interest
Step condition	
Structures	
Structure condition	
Barriers	
Barrier condition	
Signage	customised HCC signage on track (red tones)
Signage condition	provide track markers if track is not widened to clearly indicate trail
Features	Historic residential gardens, where provenance is known
Best eventual fit within NZS	Walking Track
Considerations	The existing concrete steps (historic) limit width in a short section

Pond to Pond Loop	Western
Time	
Length	
Likely predominant users	Day Visitor
Track classification	Easy Tramping Track
Track type	Short walk track in bush and passes waterfall
Track width	700 to 1200mm
Gradient	medium
Track surface	rock and gravel
Track surface condition	fair, edge needs retention at longer higher bridge
Drainage	track is rutting on eastern side of loop as a result of poor drainage and inadequate surface
Drainage condition	required
Steps	older style steps are uncomfortable, additional steps are required
Step condition	fair
Structures	two timber bridges renovated late 1990s
Structure condition	good
Barriers	
Barrier condition	
Signage	customised HCC signage on track (red tones)
Signage condition	good, but map board illustrating layout of track network in Jubilee Park would benefit
Features	Waterfall, pleasant bush, connections to other tracks
Best eventual fit within NZS	Walking Track
Considerations	Some poor quality steps and odd short steep section. Odd narrow section.

Gaskill Grove	Western
Time	5 min
Length	387m
Likely predominant users	Short Stop Traveller
Track classification	Short Walk
Track type	well defined, bush track, passing by ex-house sites of local historical interest
Track width	750mm
Gradient	medium, comfortable, undulating grade
Track surface	lime stabilised top course
Track surface condition	poor maintenance of track edges has shrunk the surface markedly
Drainage	good
Drainage condition	poor maintenance is beginning to result in ruts
Steps	timber
Step condition	good
Structures	timber boardwalk and retaining
Structure condition	excellent
Barriers	
Barrier condition	
Signage	customised HCC directional and interpretation signage on-track, Standard HCC signage on-street
Signage condition	good
Features	remnants of residential gardens, which were abandoned in the 1960s
Best eventual fit within NZS	Short Walk
Considerations	Could contribute to active transport network if similar quality track linked to Normandale overbridge

Panorama	Western
Time	10 min
Length	
Likely predominant users	Short Stop Traveller
Track classification	Short Walk
Track type	Well defined, short all weather track through bush along residential fringe, linking suburbs
Track width	50 to 300mm width has shrunk considerably since 1990s construction, result of poor maintenance
Gradient	medium
Track surface	lime stabilised to width requires attention
Track surface condition	fair, section of 35 steps, erosion of track surface by water, short narrow section.
Drainage	timber cross drains
Drainage condition	poor
Steps	many
Step condition	fair, some uneven
Structures	
Structure condition	
Barriers	timber handrail
Barrier condition	good
Signage	Standard HCC on-track signage
Signage condition	good
Features	Mature remnant Tawa
Best eventual fit within NZS	Short Walk
Considerations	Add interpretation board about remnant Tawa visible, add retention at outer track edge

Arahiwi Upper	Western
Time	10 min
Length	279m
Likely predominant users	Day Visitor
Track classification	Walking Track
Track type	short, well formed, all weather track through regenerating bush along residential fringe, linking roads.
Track width	980 to 1200mm could be widened to 1200mm
Gradient	easy
Track surface	lime stabilised top course
Track surface condition	good, a path of loose surfacing is a little slippery
Drainage	benched track with good cross fall
Drainage condition	excellent
Steps	timber, standard construction, connecting to Arahiwi Grove
Step condition	good
Structures	small timber bridge
Structure condition	excellent
Barriers	timber
Barrier condition	excellent
Signage	standard HCC on-track and on-street signage
Signage condition	excellent
Features	attractive short-cut into Belmont Regional Park and provides loop opportunities for fitness walkers/runners and mountain bikes
Best eventual fit within NZS	Walking Track Complies with NZS requirements
Considerations	Professional design and construction in 2007

Arahiwi Lower	Western
Time	10 min
Length	328m
Likely predominant users	Day visitor
Track classification	Walking Track
Track type	short, well formed, all weather track linking Arahiwi Grove to Oceanview
Track width	600 to 800mm
Gradient	easy, undulating
Track surface	earth, gravel, rock
Track surface condition	would benefit from surfacing entire length with compacted top course
Drainage	cross fall of track
Drainage condition	good but crosstalk is a little to exaggerated in places
Steps	timber
Step condition	good but one section would benefit from alterations
Structures	
Structure condition	
Barriers	
Barrier condition	
Signage	Standard HCC on-street and on-track signage
Signage condition	
Features	Was constructed with digger, which, in hindsight, was too big
Best eventual fit within NZS	Walking Track
Considerations	reducing number of steps would be more inviting for mountain bikers heading into Belmont Regional Park

Matuhi Track	Western
Time	10 min
Length	441m
Likely predominant users	Day Visitor
Track classification	Walking Track
Track type	Short track through mature remnant bush along residential fringe, linking roads.
Track width	800mm
Gradient	easy
Track surface	earth and lime stabilised top course
Track surface condition	width of gravel surface needs to be addressed
Drainage	some boggy patches
Drainage condition	
Steps	
Step condition	
Structures	timber bridge
Structure condition	good
Barriers	timber handrail over culvert
Barrier condition	good
Signage	standard HCC signage on-track
Signage condition	
Features	Stunning bush including mature Nikau. Stream.
Best eventual fit within NZS	Short Walk, Walking Track
Considerations	

Avonlea to Meadowbank Track	Western
Time	1 min
Length	
Likely predominant users	Day Visitor
Track classification	Short walk
Track type	
Track width	
Gradient	
Track surface	
Track surface condition	
Drainage	
Drainage condition	
Steps	
Step condition	
Structures	
Structure condition	
Barriers	
Barrier condition	
Signage	
Signage condition	
Features	
Best eventual fit within NZS	
Considerations	professionally designed and constructed (from new) in 2008, links new subdivision with Matuhi-Avonlea Track

Bertram Track	Western
Time	12min
Length	220m
Likely predominant users	Day Visitor
Track classification	Tramping Track
Track type	Short, well formed track through bush gully up to Palm Grove
Track width	300mm to 2m
Gradient	medium
Track surface	earth, gravel, roots, rock
Track surface condition	fair, loose gravel is a little slippery in parts, cross fall is too steep in parts
Drainage	timber box drain
Drainage condition	fair, some boggy areas
Steps	4 flights of timber steps
Step condition	good, additional required in lower section, timber retention of edge would benefit
Structures	bridges
Structure condition	good
Barriers	
Barrier condition	
Signage	Interpretation panel about Bertram at lower track entrance plus standard HCC on-street signage
Signage condition	good
Features	Stream. Nikau.
Best eventual fit within NZS	Walking Track
Considerations	No legal access for track users exiting to Palm Grove Uneven steps and narrow width in parts particularly bridges.

Park Hill Track	Western
Time	10 min
Length	
Likely predominant users	Day Visitor
Track classification	Walking Track
Track type	Short, well formed, all weather track through bush gully along residential fringe, linking key suburban roads and reserve.
Track width	750 to 2000mm
Gradient	medium
Track surface	compacted top course
Track surface condition	good
Drainage	
Drainage condition	
Steps	many timber steps of various dimensions
Step condition	good
Structures	bridge over stream
Structure condition	fair
Barriers	
Barrier condition	
Signage	standard HCC on-street signage
Signage condition	good
Features	Stream with glow worms but track has very low profile street frontage
Best eventual fit within NZS	Walking Track but cycle friendly
Considerations	Hill Road side upgraded in 2007 and piece of track between stream and Park Road installed in 2008, both by specialised contractor

Tawhai Route	Northern
Time	60 min 60min up 40 min down
Length	24-Nov-04
Likely predominant users	Day Visitor
Track classification	Route
Track type	Combination Walking track / tramping track through mature remnant and advanced regenerating bush to firebreak
Track width	
Gradient	very, very steep requires ruggedness and good level of fitness
Track surface	
Track surface condition	
Drainage	
Drainage condition	
Steps	
Step condition	
Structures	several bridges are required if upgrading proceeds
Structure condition	
Barriers	
Barrier condition	
Signage	standard HCC on-Street and on-track signage
Signage condition	good, sign on ECNZ Road intersection frequently stolen
Features	Stunning bush including mature Rimu, Beech, Rata, Nikau and ground ferns. Streams.
Best eventual fit within NZS	Walking Track or Easy Tramping Track.
Considerations	Stream crossings, benching and track width, very steep and narrow upper third of track.

Kamahi Track	Northern
Time	60 min (uphill) 40 min (downhill)
Length	24-Dec-04
Likely predominant users	Day Visitor
Track classification	Tramping Track
Track type	Combination Walking track / tramping track through mature remnant and advanced regenerating bush to firebreak
Track width	300 to 750mm could easily be widened to 750mm
Gradient	steep requires good level of fitness
Track surface	earth, gravel, roots, rock, track direction poorly defined in parts
Track surface condition	good
Drainage	1 under track near start
Drainage condition	blocked, probably boggy patched following wet weather
Steps	
Step condition	
Structures	boardwalks
Structure condition	good
Barriers	
Barrier condition	
Signage	
Signage condition	
Features	Stream. Native bush. Lycopodium. Views over Whitemans Valley farm from top.
Best eventual fit within NZS	Walking Track or Easy Tramping Track.
Considerations	Realign track out of stream bed for 100m section, very steep, especially in lower parts but improvements are realistic

Stokes Valley Stream	Northern
Time	
Length	
Likely predominant users	Urban Resident
Track classification	Walking Track
Track type	concrete and gravel path close to stream and amenity plantings
Track width	
Gradient	
Track surface	concrete and gravel path
Track surface condition	fair
Drainage	
Drainage condition	
Steps	
Step condition	
Structures	
Structure condition	
Barriers	
Barrier condition	
Signage	
Signage condition	
Features	enhancements largely provided by Stokes Valley Rotary Club
Best eventual fit within NZS	Path
Considerations	Developments are located close to the artificial channel and are vulnerable to flooding
Soil Bureau Loop	Northern
Time	
Length	
Likely predominant users	
Track classification	Tramping Track
Track type	old fram path used to service bureau operations, surrounding land prev grazed until 1995
Track width	
Gradient	
Track surface	remnants of wide, asphalt path, good grade
Track surface condition	poor
Drainage	
Drainage condition	
Steps	
Step condition	
Structures	
Structure condition	
Barriers	
Barrier condition	
Signage	
Signage condition	
Features	
Best eventual fit within NZS	Walking Track
Considerations	Does not need to be reinstated with asphalt, just something to cope with ute or quad/trailer
Rata St Loop	Eastern
Time	60min
Length	2488m excludes reservoir driveway
Likely predominant users	Day Visitor
Track classification	Tramping Track
Track type	Short walk track through bush along residential fringe, linking to ECNZ Road
Track width	300mm plus
Gradient	steep
Track surface	earth, rock, roots, gravel - poorly defined in places
Track surface condition	poor, some boggy areas
Drainage	poor construction and cross-fall causes water to deeply rut sections of track
Drainage condition	
Steps	many, various construction methods
Step condition	poor
Structures	1 boardwalk, 3 bridges
Structure condition	
Barriers	timber
Barrier condition	
Signage	standard HCC on-street and on-track signage
Signage condition	good
Features	Views over valley Avalon to Korokoro. Ground ferns, Beech.
Best eventual fit within NZS	Walking Track
Considerations	This attractive location warrants upgrading and redirecting sections of the Loop

Harry Todd Track	Wainuiomata
Time	
Length	2850m
Likely predominant users	Short Stop Traveller
Track classification	Tramping Track
Track type	Loop walk track through bush along residential fringe.
Track width	200mm plus
Gradient	medium, but altering Hine Road entry could reduce this
Track surface	earth, rock, roots, grass
Track surface condition	fair, needs retention
Drainage	some boggy patches
Drainage condition	lack of cross fall has resulted in scouring
Steps	timber
Step condition	poor
Structures	5 timber bridges
Structure condition	
Barriers	1 timber handrail
Barrier condition	
Signage	inadequate
Signage condition	
Features	Nice bush, views over valley and out to coast and snow covered (No Suggestions), Beech, Podocarps, Lycopodium.
Best eventual fit within NZS	Short Walk
Considerations	upgrading the Hine Road entrance would lift the standard and profile of this track markedly
Mt Crowther Track	Wainuiomata
Time	
Length	
Likely predominant users	Day Visitor
Track classification	Tramping Track
Track type	
Track width	
Gradient	medium
Track surface	earth
Track surface condition	
Drainage	
Drainage condition	
Steps	
Step condition	
Structures	
Structure condition	
Barriers	
Barrier condition	
Signage	not signed
Signage condition	requires signage
Features	uninteresting but longer trail, which is used by Police vehicles to service communication equipment
Best eventual fit within NZS	Walking Track
Considerations	Can be used as a link to make a loop walk, using Harry Todd Track
Black Creek South	Wainuiomata
Time	
Length	
Likely predominant users	Urban Residents
Track classification	Walking Track NB not fully complying because it is not surfaced
Track type	grass track between Moohan Street/Main Road corner and Petrie Street
Track width	
Gradient	very easy
Track surface	grass
Track surface condition	fair but variable
Drainage	prevent year round use
Drainage condition	
Steps	
Step condition	
Structures	
Structure condition	
Barriers	
Barrier condition	
Signage	
Signage condition	
Features	not an all weather surface and performs poorly following wet weather
Best eventual fit within NZS	Path
Considerations	all weather path would benefit recreational walkers and cyclists and active transport

Black Creek Central	Wainuiomata
Time	
Length	
Likely predominant users	Urban Residents
Track classification	Walking Track NB not fully complying because it is not surfaced
Track type	grass track between Petrie Street and Nelson Crescent
Track width	
Gradient	very easy
Track surface	grass
Track surface condition	fair but variable
Drainage	prevent year round use
Drainage condition	
Steps	
Step condition	
Structures	
Structure condition	
Barriers	
Barrier condition	
Signage	
Signage condition	
Features	not an all weather surface and performs poorly following wet weather
Best eventual fit within NZS	Path
Considerations	all weather path would benefit recreational walkers and cyclists and active transport

Black Creek North	Wainuiomata
Time	
Length	
Likely predominant users	Urban Residents
Track classification	Walking Track NB not fully complying because it is not surfaced
Track type	grass track between Nelson Crescent and Norfolk Street
Track width	
Gradient	very easy
Track surface	grass
Track surface condition	fair but variable
Drainage	prevent year round use
Drainage condition	
Steps	
Step condition	
Structures	
Structure condition	
Barriers	
Barrier condition	
Signage	
Signage condition	
Features	not an all weather surface and performs poorly following wet weather
Best eventual fit within NZS	Path
Considerations	all weather path would benefit recreational walkers and cyclists and active transport

Poole Crescent Track	Wainuiomata
Time	
Length	1300m
Likely predominant users	Short Stop Traveller
Track classification	
Track type	Easy Tramping Track, could easily be upgraded to Short Walk or even Path standard
Track width	nil to 2m plus
Gradient	almost flat
Track surface	gravel and grass
Track surface condition	fair
Drainage	gravel road below Poole Crescent needs attention
Drainage condition	ponds in places for long periods
Steps	
Step condition	
Structures	1 boardwalk, 1 bridge
Structure condition	good
Barriers	
Barrier condition	
Signage	
Signage condition	
Features	passes rivers, sports fields and connects to Main Road, Poole Crescent and Hine Road
Best eventual fit within NZS	Short Walk
Considerations	Important, easy link, warrants all weather standard and upgrading the Hine Road end, last 20m

Rotary Park Trail	Wainuiomata
Time	
Length	
Likely predominant users	Short Stop Traveller
Track classification	Easy Tramping Track
Track type	Trail could easily be upgraded to Short Walk or even Path, connects to Gibbs Crescent
Track width	variable
Gradient	almost flat
Track surface	gravel and grass
Track surface condition	fair
Drainage	gravel road below Poole Crescent needs attention
Drainage condition	ponds in places for long periods
Steps	
Step condition	
Structures	1 boardwalk, 1 bridge
Structure condition	good
Barriers	
Barrier condition	
Signage	
Signage condition	
Features	overlooks Black Creek/Wainuiomata River confluence, attractive trees
Best eventual fit within NZS	Short Walk
Considerations	Important, easy link, warrants all weather standard and upgrading the Hine Road end, last 20m
Wainuiomata Lookout	Wainuiomata
Time	
Length	
Likely predominant users	Urban residents
Track classification	Short Walk
Track type	short sealed trail between car park and lookout
Track width	
Gradient	medium
Track surface	sealed surface
Track surface condition	
Drainage	
Drainage condition	
Steps	
Step condition	
Structures	
Structure condition	
Barriers	
Barrier condition	
Signage	
Signage condition	
Features	
Best eventual fit within NZS	Path
Considerations	fantastic views over Harbour and lower Hutt Valley
Westhill Track	Harbour
Time	
Length	
Likely predominant users	Day Visitor
Track classification	Tramping Track
Track type	
Track width	
Gradient	
Track surface	earth
Track surface condition	fair
Drainage	
Drainage condition	boggy patches
Steps	
Step condition	
Structures	
Structure condition	
Barriers	
Barrier condition	
Signage	none
Signage condition	
Features	poor entry from Westhill Gr, very narrow strip of land available for track, plus difficult access
Best eventual fit within NZS	Walking Track

Westhill Pipe Track	Harbour
Time	
Length	
Likely predominant users	Day Visitor
Track classification	Tramping Track
Track type	
Track width	
Gradient	
Track surface	earth
Track surface condition	fair
Drainage	
Drainage condition	
Steps	timber, many
Step condition	more required near creek
Structures	
Structure condition	
Barriers	
Barrier condition	
Signage	none
Signage condition	
Features	
Best eventual fit within NZS	Walking Track
Korimako Track	Harbour from pond to pavillion, via Korimako Road
Time	25min
Length	
Likely predominant user	Short Stop Traveller
Track classification	Walking Track
Track type	Well defined loop walk track through beech forest along residential fringe
Track width	1200 to 2500mm
Gradient	medium
Track surface	mixture of gravels, earth, rock, roots and asphalt, outside edge requires retention in places
Track surface condition	poor, given popularity
Drainage	7 timber box channels but lack of cross-fall and cross-drains is scouring tracks
Drainage condition	fair additional drainage required
Steps	in ground timber steps, more required
Step condition	fair
Structures	
Structure condition	
Barriers	
Barrier condition	
Signage	standard HCC on-track signage
Signage condition	
Features	Pond, nice bush, views over harbour, cafés, tennis courts, beach, wharf, picnic areas.
User groups	Locals and visitors.
Best eventual fit within NZS	Short Walk
Considerations	Better steps and track quality will elevate this to a Short Walk and provide good walking for people unable to manage EHRP Tracks
Days Bay Lookout Track	Harbour
Time	5 min return
Length	
Likely predominant users	Short Stop Traveller
Track classification	Tramping Track
Track type	Poor quality track through bush to lookout providing fantastic views of Days Bay and Wellington Harbour
Track width	100 to 300mm
Gradient	medium
Track surface	clay and roots, rutted, uneven surface, warrants some realigning to achieve lower gradient
Track surface condition	poor
Drainage	noticeable water damage
Drainage condition	
Steps	timber, more required, perhaps with landings
Step condition	poor
Structures	warrants a new deck with seating
Structure condition	
Barriers	timber barrier defining edge of lookout
Barrier condition	
Signage	
Signage condition	
Features	Views over Days Bay and harbour.
Best eventual fit within NZS	Short Walk
Considerations	Could easily be upgraded and widened to address track quality

Lower Pond Loop	Harbour
Time	4 min
Length	
Likely predominant users	
Track classification	Tramping track
Track type	Short loop walking track through bush.
Track width	300mm plus
Gradient	easy
Track surface	side of track needs retention
Track surface condition	
Drainage	
Drainage condition	
Steps	steps needed
Step condition	
Structures	bridge
Structure condition	
Barriers	
Barrier condition	
Signage	
Signage condition	Bush
Features	Locals and visitors.
Best eventual fit within NZS	Walking track.
Considerations	Address width and surface, perhaps this track is now redundant? Several side tracks need to be physically closed to contain use to track.

Mawson Street Track	Eastern
Time	
Length	
Likely predominant users	Day Visitor
Track classification	Easy Tramping Track
Track type	links Mawson Street with Whites Line East Track
Track width	
Gradient	medium
Track surface	
Track surface condition	
Drainage	
Drainage condition	
Steps	
Step condition	
Structures	
Structure condition	
Barriers	
Barrier condition	
Signage	
Signage condition	
Features	
Best eventual fit within NZS	Walking Track
Considerations	The unmanaged link to the unmanaged Firebreak needs to be considered strategically

Whites Line East Track	Eastern
Time	
Length	
Likely predominant users	Day Visitor
Track classification	Walking Track
Track type	earth, roots and some lime stabilised top course on lower section
Track width	
Gradient	medium
Track surface	gravel, earth
Track surface condition	fair
Drainage	
Drainage condition	
Steps	timber, in ground
Step condition	good
Structures	timber bridges
Structure condition	good
Barriers	
Barrier condition	
Signage	Artistic map board at Whites Line East entrance, otherwise standard HCC on-street and on-track signage
Signage condition	good
Features	currently the easiest track to ECNZ Ridge along entire Eastern Hills
Best eventual fit within NZS	Walking Track
Considerations	unmanaged side tracks need to be considered strategically

Ngaponga	Eastern
Time	
Length	
Likely predominant users	Day Visitor
Track classification	Walking Track
Track type	link between Te Whiti Firebreak and Whites Line East Track
Track width	links Whites Line East Track to Te Whiti Firebreak at mid level
Gradient	
Track surface	earth
Track surface condition	fair, requires application of material
Drainage	
Drainage condition	requires some attention
Steps	
Step condition	
Structures	
Structure condition	
Barriers	
Barrier condition	
Signage	
Signage condition	
Features	
Best eventual fit within NZS	Walking Track
Considerations	
Spoonhill, incl 491 diversion	Wainuiomata
Time	
Length	
Likely predominant users	MTB riders
Track classification (IMBA)	Moderate
Track type	poorly formed downhill trail with some steep sections that many riders would push
Track width	
Gradient	steep
Track surface	
Track surface condition	clay, roots
Drainage	ruttled, slippers after wet weather
Drainage condition	
Steps	earth
Step condition	
Structures	timber rail ramp, authorised
Structure condition	
Barriers	timber barriers on ramp
Barrier condition	
Signage	
Signage condition	required
Features	unauthorised jumps are an ongoing problem and safety issue
Best eventual fit within NZS	any upgrading needs to avoid steps to cater for cyclists
Considerations	dual use, possibly has developed, following line of desire, began as walkers track
Spoonhill Staircase	Wainuiomata
Time	
Length	
Likely predominant users	MTB riders
Track classification (IMBA)	Very Hard
Track type	technical trail, ridden downhill but walked both ways
Track width	
Gradient	steep
Track surface	earth, very steep
Track surface condition	ruttled, loose in dry weather, slippery
Drainage	
Drainage condition	
Steps	earth
Step condition	
Structures	
Structure condition	
Barriers	
Barrier condition	
Signage	
Signage condition	required
Features	very difficult to ride, very steep to walk up and down
Best eventual fit within NZS	
Considerations	

Jungle Gym	Wainuiomata
Time	
Length	
Likely predominant users	MTB riders some use by fitness walkers as part of loop
Track classification (IMBA)	Moderate
Track type	easiest MTB trail between Waiu Street and summit of Wainuiomata Hill
Track width	steep
Gradient	
Track surface	limed stabilised top course, entire length
Track surface condition	
Drainage	cross drains
Drainage condition	
Steps	
Step condition	
Structures	small timber bridge, complies with SNZ handbook
Structure condition	
Barriers	
Barrier condition	
Signage	required
Signage condition	
Features	short sight lines, planned to become an uphill track once an easy downhill track is developed for
Best eventual fit within NZS	
Considerations	constructed by volunteers with some assistance from expert contractors

Wetland Loop	Wainuiomata
Time	
Length	
Likely predominant users	MTB riders
Track classification (IMBA)	Easy
Track type	Beginners trail though bush no exit, must go there and back on same trail currently
Track width	
Gradient	almost flat
Track surface	lime stabilised top course
Track surface condition	motorbike use has been problematic
Drainage	cross drains, benching
Drainage condition	excellent
Steps	none
Step condition	
Structures	
Structure condition	
Barriers	
Barrier condition	
Signage	required
Signage condition	
Features	very easy, also
Best eventual fit within NZS	
Considerations	Warrants extending to form loop around swamp, back to Waiu Street

Beeline	Wainuiomata
Time	
Length	
Likely predominant users	MTB riders
Track classification (IMBA)	Very Hard
Track type	
Track width	
Gradient	steep
Track surface	earth and roots
Track surface condition	unsurfaced
Drainage	
Drainage condition	
Steps	
Step condition	
Structures	set of timber jumps, authorised
Structure condition	
Barriers	
Barrier condition	
Signage	required
Signage condition	
Features	one drop off and one wall ride
Best eventual fit within NZS	
Considerations	

Labyrinth	Wainuiomata
Time	
Length	
Likely predominant users	
Track classification (IMBA)	Moderate
Track type	uphill link between Jungle Gym/ Wainui Road and Spoonhill
Track width	
Gradient	medium
Track surface	lime stabilised top course
Track surface condition	wearing well
Drainage	benched, no drainage issues to date
Drainage condition	
Steps	
Step condition	
Structures	timber decking over routes
Structure condition	
Barriers	
Barrier condition	
Signage	required
Signage condition	
Features	
Best eventual fit within NZS	
Considerations	built as an uphill track but can be ridden two ways. Tight switchbacks

SAMPLE Ward

Time	
Length	
Likely predominant users	
Track classification	
Track type	
Track width	
Gradient	
Track surface	
Track surface condition	
Drainage	
Drainage condition	
Steps	
Step condition	
Structures	
Structure condition	
Barriers	
Barrier condition	
Signage	
Signage condition	
Features	
User groups	
Current fit within NZS	
Best eventual fit within NZS	
Considerations	